PILLAR FIRE HYDRANT WITH BREAK SYSTEM type LNH1

<Two in one = hydrant + isolating pre-valve>

<Double reliability = use even when main valve is defective>

PROCUREMENT DATA:*1 **<great flow (Kv= 150 m³/h)=minor fire damage>**



Appearance

* Name: Pillar fire hydrant with break system
* Made in accordance with the SRPS EN14384 standard, type "A"*2 CE
* Nominal sizes DN80, PN16. * Closing with the main valve "from above".
* With isolation "pre-valve", closing "from below". * With control valve.
* Activation without or with an additional tool.
* The possibility of blocking unauthorized use.
* Flow (for Di=2x50); Kv=min.145m³/h
* Activation moment: MOT=max.60Nm.
* Repair of the main valve; the other hydrants remain in operation, without digging up the ground and without dismantling the hydrant.
* Drainage system "all outside"; repair without dismantling the hydrant.
* Outlets tiled toward the ground for 25°.
* Breakage due to force F; no damage to the lower part of hydrant.*3
* Breaking moment M=max.1200daN. *3

* Inlet connection : → Flange EN1092-2 (Du80, PN16) (Du100, PN16) / Particular request, "describe"
* Nominal height Hi: → (1300) (1500) (1800) mm / Particular request, "describe"
* Outlets Di: → (2x50+1x65) mm
* Outlet couplings: → (2xC+1xB) DIN, system "storz" / Specify label and standard
* Drainage system: → (D1)(D2) / Without
* Medium: Water → (technical) / (drinking)
* Colors of external surfaces:
  - aboveground part (without pipe): → red / special request
  - underground part: black
* **Warranty period: 5 years.**
* Submit documents:
- "Prospect";
- "Test Report",issued by an "authorized body";
- "Certificate of Conformity", issued by an "authorized body"

*1 → If necessary, "omit/add"

*2 → **The standard determines the min. performance = "the least good allowed" hydrant.**



Appearance:
1. Inlet flange
2. Isolation "**pre-valve**" **(closing from below)**
3. Obturator - "**main valve**" **(closing from above)**
4. Body **4.1 Place of breakage,** due to the impact of force F
5. Cap (keyless activation)
6. Blocking of unauthorized use
7. **Control valve** (**safety**; sealing)
8. Outlet couplings
9. Ident plate ("CE", "Kv",...)
10. **Drainage system**: (not defined by the standard)

type **D1**:
10.1 Drain valve 10.2 Drain pipe
10.3 Stone → (16÷31) mm*4

type **D2**:
10.1 Drainage valve
10.2 Drain pipe → (L=?) mm
10.3 Distribution pipe 10.4 Wire basket*4
10.5 Stone → (16÷31) mm*4
10.6 Cover 10.7 Plastic foil*4
11. Arch with foot EN545*4

*4 → **Provided by the buyer**

TECOOP - ENG D.O.O
INDUSTRIJSKI INŽENJERING

Srbija - 26000 PANČEVO, Savska 12 - 14.
Tel. +381 13 346226 Tel./Fax +381 13 346042
www.tecoop.co.rs / tecoopeng@mts.rs

PILLAR FIRE HYDRANT WITH BREAK SYSTEM type LNH1

<Two in one = hydrant + isolating pre-valve>
<Double reliability = use even when main valve is defective>
<great flow (Kv= 150 m³/h)=minor fire damage>

Basic technical characteristics:

* **Safe = complies with** the requirements of the **EN 14384 standard** = CE
* **Purpose**: Taking water from underground pipelines for **fire fighting and communal needs**
* **See "Procurement data" P1/2**
* **Flow**: **Kv=150m³/h, for Di=2x50**
* **Moment of activation MOT:max 50 Nm (Class 1)**
* **Breaking force** ..... F=1100 daN
* **In case of breakage: the hydrant remains closed, and part of the hydrant is below the fracture site remains undamaged**
* **Foundation** .....
* **Weight** ..... ~ (53÷67) daN for Hi (1300÷1800) mm
* **Materials**:
  - hydrant body castings ..... nodular cast
  - cap, and output couplings ..... aluminium
  - sealants ..... polypropylene/elastomers
  - pipe of body, spindle, and obtutator seat ..... stainless steel

*3

Load scheme
(obligation under the standard)



Advantages:

* **Two ways of use = double reliability**
  - closing with the **main valve (3)**, from above **(regular work),**
  - closing with a **pre-valve (2)**, from below **(extraordinary work),**
* Isolation **pre-valve (2) inside the hydrant**, automatic, self-blocking, **which enables**:
  - **that the other hydrants remain in operation even when the main valve (3) malfunction,**
  - **to omit** a separate isolation **valve in front of the hydrant,**
  - **lower cost** of procurement and maintenance of the **hydrant network,**
  - **the use of a hydrant even when the main valve (3) is malfunction,**
* **Large flow: (Kv=150 m³/h**; for Di=2x50); **less fire damage.**
* **Control valve (7) = great safety of the executor, prevention of hydrant freezing.**
* **Activation without additional tools**, by turning the cap (5).
* **Easy activation: (class 1, MOT < 50 Nm) longer service life**.
* **Possibility of blocking (6) unauthorized use.**
* **High reliability of closing**; impermeablility even after 1000 closings.
* **Outlets tilted (25°) down, longer service life** of fire hoses.
* **The main valve seal is conical**, **self-flushing** = dirt retention prevented = **longer service life.**
* **Very easy hydrant maintenance:**
  - **Replacing the main valve seal (3)**; **without digging up the ground and without dismantling the body (4).**
  - **Possibility (7) of checking the correctness of the drain and main valve.**
  - **Repair of the drainage valve (10.1)**; **from the outside**, partial excavation, and **without dismantling the hydrant.**
* **Long warranty period 5 years.**
* **Probably the best, and the most economical hydrant available**

Documents accompanying the delivery of hydrant:

* Declaration of Performance,
  or Certificate of Constancy of Performance
* Instruction for safety work (installation, handling, inspection, maintenance, warranty)

Flow of hydrant:



$Q = K_v \times (1000\Delta p / \rho)^{1/2}$
- flow..... Q [m³/h]
- flow coefficient..... K_v [m³/h]
- pressure difference..... Δp [bar]
- water density..... ρ [kg/m³]

TECOOP - ENG D.O.O
INDUSTRIJSKI INŽENJERING

Srbija - 26000 PANČEVO, Savska 12 - 14.
Tel. +381 13 346226 Tel./Fax +381 13 346042
www.tecoop.co.rs / tecoopeng@mts.rs